180622

t the state of the

and gripped to the control of the first and there is not all the second of the control of the co

make in inflating properties of the second sections of the second section of the second

CORNER RECORD SURVEYOR'S CERTIFICATE I, MARK D. MORBERG, A PROFESSIONAL LAND SURVEYOR LICENSED IN THE STATE OF NEVADA, CERTIFY THAT: THIS CORNER RECORD REPRESENTS THE ESTABLISHMENT, RESTORATION, OR RECOVERY OF A CORNER OR ACCESSORY TO A CORNER CONDUCTED UNDER MY DIRECT SUPERVISION. THE MONUMENT OR ACCESSORIES PERPETUATED UE WITHIN SECTION 32, T.20 NORTH, R.53 EAST, M.D.M. EUREKA COUNTY, NEVADA AND THE ESTABLISHMENT OR RESTORATION WAS COMPLETED ON NOVEMBER 5, 2001. 3. THIS CORNER RECORD HAS BEEN FILED PURSUANT TO NRS 329.140 OR 329.150 AND COMPUES WITH THE PROVISIONS OF NAC 329.010 AND ANY LOCAL ORDINANCES IN EFFECT ON THE DATE THAT THE ESTABLISHMENT OR RESTORATION WAS COMPLETED. 4. THE MONUMENT OR WITNESS MONUMENT AND ACCESSORIES FOUND ARE OF THE CHARACTER SHOWN, OCCUPY THE POSITIONS INDICATED, AND ARE OF SUFFICIENT NO SUHVEYOR MARK D. MORBERG & NC 12466 MARK D. MORBERG P.L.S. 12/10/02 PT. No. 6148 NEVADA NO. 12466 N 14366557 E 1916945 EVF 12/31/03 Section 32, Township 20 North, Range 53 East, MDM PT. No. 6164 N 14366537 E 1914194 FND. 5/8" REBAR RLS 827 FND. 5/8" REBAR NO TAG NTS LEGEND PT. No. 5378 FND. GLO BRASS CAP FNO. GLO BRASS CAP 1933, STAMPED 1/4" (FOUND CADASTRAL N 14365193 E 1912890 STAMPED "1/4" 1927 OŅ CORNER AS DESCRIBED BENT PIPE. SECTION 32 PT. No. 5380 N 14365235 E 1918337 RECORDER'S INFORMATION EOOK *35*7 PAGE 046 OFFICIAL RECORDS BASIS OF COORDINATES NAD 1983 (94 HARN ADJUSTMENT) Stantec Consulting due. UTM, ZONE 11, US SURVEY FEET 02 DEC 23 PH 4: 26 NOTES THE ABOVE REFERENCED CORNER(S) WERE RECOVERED AS PART OF THE SIERRA PACIFIC POWER COMPANY FALCON PROJECT. HITTED LEATHE CORDER FLES 14.00 180622 JOB No. 80400400 JANUARY 2002 SHEET 1 OF 1