




A MAP OF THE ETAK LODGE CLAIMS

Ts. 34 & 35 N., R. 48 E., M.D.M.

EUREKA COUNTY, NEVADA



NOTE: All section lines are projected.

NOTE: All corner, side center and location monuments are 4" x 4" x 4" wood posts.

BASIS OF BEARING:
The South line of the Southeast 1/4 of section 34, T. 35 N., R. 48 E., M.D.M. is assumed to bear East and West.

TIE: The Southeast corner of ETAK 295 is 50 feet South and 0 feet West of the Southeast corner of section 34, T. 35 N., R. 48 E., M.D.M.




DATES OF LOCATION:
ETAK 279 to 314 on May 29, 1992.

FILED AT THE REQUEST OF *Gold Fields*
on *Aug 3* 19*92*, at *39* mins, past *10* P.M.
RECORDS, EUREKA COUNTY, NEVADA M. N. REBALEATI, Recorder
File No. *141840* Fee \$ *5.40*

GOLD FIELDS MINING COMPANY			
1687 Cole Blvd., Golden, Colorado 80401-3301			
SURVEYED BY	DATE	CHKD. BY	
D.S.	7-11-92	<i>E. SCHAAF</i>	<i>E. SCHAAF & ASSOCIATES</i>
DRAWN BY	SCALE	ACCT. NO.	
S.B.	1"=500'	J9248C2I	

141840

A MAP OF THE ETAK LODE CLAIMS
T. 34 N., R. 48 E., M.D.M.
LANDER & EUREKA COUNTIES, NEVADA



NOTE: All section lines are projected.

NOTE: All corner, side center and location monuments are 4" x 4" x 4' wood posts.

BASIS OF BEARING:
The North line of the Northwest 1/4 of section 20, T. 34 N., R. 48 E., M.D.M. is assumed to bear East and West.

TIE: The Northwest corner of ETAK 237 is 50 feet North and 50 feet West of the Northwest corner of section 20, T. 34 N., R. 48 E., M.D.M.

DATES OF LOCATION:
ETAK 236 to 241 on May 27, 1992.

FILED AT THE REQUEST OF Gold Fields
on Aug 3 19 92, at 39 mins. past 4 P. M.
RECORDS OF EUREKA COUNTY, NEVADA M. N. REBALEATI, Recorder
File No. 111840 Fee \$ 46

GOLD FIELDS MINING COMPANY	
1687 Cole Blvd., Golden, Colorado 80401-3301	
SURVEYED BY D.S.	DATE 8-18-92
DRAWN BY S.B.	SCALE 1"=500'
CHKD. BY E. SCHAAF & ASSOCIATES 807 PALMER DELTA, COLORADO 80410 U.S. 18487-U.S. MINERAL SURVEYOR	
ACCT. NO. J9248C2G	