180635

The second secon

CORNER RECORD SURVEYOR'S CERTIFICATE I, MARK D. MORBERG, A PROFESSIONAL LAND SURVEYOR LICENSED IN THE STATE OF NEVADA, CERTIFY THAT: 1. THIS CORNER RECORD REPRESENTS THE ESTABLISHMENT, RESTORATION, OR RECOVERY OF A CORNER OR ACCESSORY TO A CORNER CONDUCTED UNDER MY DIRECT SUPERVISION. THE MONUMENT OR ACCESSORIES PERPETUATED UE WITHIN SECTION 3, T.30 NORTH, R.49 EAST, M.D.M. EUREKA COUNTY, NEVADA AND THE ESTABLISHMENT OR RESTORATION WAS COMPLETED ON OCTOBER 18, 2000. THIS CORNER RECORD HAS BEEN FILED PURSUANT TO NRS 329.140 OR 329.150 AND COMPLIES WITH THE PROVISIONS OF NAC 329.010 AND ANY LOCAL ORDINANCES IN EFFECT ON THE DATE THAT THE ESTABLISHMENT OR RESTORATION WAS COMPLETED. THE MONUMENT OR WITNESS MONUMENT AND ACCESSORIES FOUND ARE OF THE CHARACTER SHOWN, OCCUPY THE POSITIONS INDICATED, AND ARE OF SUFFICIENT DURABILITY. MARK D. MORBERG 9 MARK D. MORBERG PLANO 12466 PT. No. 5139 3/20/02 Section 3, Township 30 North, Range 49 East, MDM FND. 11"x8"x7" NOTCHED STONE. 4 NOTCHES ON WEST SIDE, 2 NOTCHES ON EAST. "CC" ON SOUTH, MARKED BY A T POST. PT. No. 5137 FND. 16"x14"x8" NOTCHED STONE, 3 NOTCHES ON WEST-SIDE, 3 NOTCHES ON EAST, "CC" ON SOUTH, MARKED BY MTS A T POST. LEGEND FOUND CADASTRAL CORNER AS DESCRIBED SECTION 3 FND. 18"x10"x8" NOTCHED STONE, J NOTCHES ON EAST SIDE, 5 NOTCHES ON SOUTH' & A 1/2" REBAR NOT TAGGED ADJACENT, MARKED BY A 3" POST. PT. No. 5138 N 14707542 E 1791953 BASIS OF COORDINATES RECORDER'S INFORMATION NAD 1983 (94 HARN ADJUSTMENT) UTM, ZONE 11. US SURVEY FEET NOTES: DODK 357 PAGE 059 THE ABOVE REFERENCED CORNER(S) WERE RECOVERED AS PART OF THE SIERRA PACIFIC OFFICIAL DECORDS POWER COMPANY FALCON PROJECT. Stanter Consulting dre. 02 DEC 23 PN 4:28 THE UD. FEES - 180635 JOB No. 80400400 JANUARY 2002 SHEET 1 OF 1

Application of the second state of the second state of the second second

. -. . . -