124974

Field Date 5 September 1988

CERTIFIED LAND CORNER RECORDATION

DESCRIPTION OF CORNER EVIDENCE FOUND, AND ORIGINAL RECORD (If known)		
Record: 1872 - North bet. Secs. 27 and 28.		
	80.00 Set a charred post in mou	nd with pits as per instructions
	for Corner to Secs. 21	-22-27 and 28.
	1914 - E. bet. Secs. 21 and 28;	retracing.
	80.26 I find the cor. of Secs.	21, 22, 27 and 28; falling 23 lks.
		a stake 2 ins. diam. by 14 ins.
above ground; set in the ground in a mound of earth and see below		ne ground in a mound of earth and see below see below
DESCRIPTION OF MONUMENT AND ACCESSORIES ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:		
	Set: A 2" galvanized steel pip cap inscribed as shown	e 31" long (BLM type) with brass
see below		
SKETCH, WITH COURSE AND DISTANCE TO ADJACENT CORNER IF DETERMINED IN THIS SURVEY. (May Sketch or Paste Reproduction on Reverse Side.)		
Reference: Book NV2, pages 10-11.		<u>) </u>
Record: mkd. with 2 notches on the E. and 2 notches on the S. edge.		
Continued 80.26 The cor. of Secs. 21, 22, 27 and 28.		
I destroy all traces of this cor. and its accessories and re- establish it at the same point as follows:		
	establish it at the So Sot a bacalt stone leveys	ins. 10 ins. in the ground for cor. of
secs. 21, 22, 27 and 28; mkd. with 2 notches on the E. and 2		
notches on the S. edge; dig pits 18x18x12 ins. in each sec.		
5½ ft. dist. and raise a mound of earth 4 ft. base, 2 ft.		
high E. of cor.		
		s avidance of the stone manument the
Found: As there appeared to be no evidence of the stone monument, the location for reestablishment was run in from the S½ of		shment was run in from the SI of
Section 21 and $E_{\frac{1}{4}}$ Section 21 as for a two line double propor-		
tionate reestablishment. This indicated that the mounuments		
	should be in the posit	ion of the corner RR tie fence post. In
	digging the hole to set a monument the original stone was	
	recovered which is a hard, red granite stone broken into two	
	pieces 15 x11"x8" marked with 2 notches on S. and E. alongside to E. of RR tie fence post.	
	to E. of KR tie fence	ρος.
	Set:	
	Continued	see reverse side
I, Paul N. Scherbelcertify that I have carefully participal aviewed the work done on the diagrammed corner as reported on this recordation form and approve the same of the corner as reported on this recordation form and approve the same of the corner as reported on the c		
I, Paul N. Scherbelcertify that I have carefully performed aviewed the work done on the diagrammed corner as reported on this recordation form and appraise the same of the corner as reported on this recordation form and appraise the same of the corner as reported on this recordation form and appraise the corner as reported on this recordation form and appraise the corner as reported on the corner a		
done on the diagrammed corner as reported on this recordation form and appraire the same of		
	<u> </u>	Such 6805
	Signate	ie of Surveyor Registration No.
TOTE OF TOTAL NEVADA		
ce of Clerk and Recorder,		
	County of EUREKA	100000000 10 A
3.5/		
This "corner record" was filed for record on theday of, 19.22, was noted		
		k No. 36-49
77.97. Relation		M. M. Relalect:
	cc: BLM	County Official
_		Index No T R Mer.
	Close	T R Mer.
		T R Mer.
		T R, Mer.
	12497	4 T R Mer.
		T R Mer.
		T R Mer.